

MAINTAINING INK DURING PRODUCTION

CONSISTENT INK. CONSISTENT RESULTS.



1 pH



Check the pH of the ink.



Proper pH range of ink should be 8.5 - 9.5.
pH should be checked every 30 min.

2 VISCOSITY



Check the viscosity of the ink.



Viscosity should be checked every 30 min.

3 COLOR



Check color against color standard and spectral data throughout production run.



Use the approved JM Fry color standard and/or spectral tools.

4 INK LEVELS



Check ink levels in each ink station.



Avoid low levels of ink.

GOOD PRINTING STARTS WITH CONTROL.



PRESSURE
in control



INK
in control



TEMPERATURE
in control



TIME
in control



**BETTER PRINTING.
LESS WASTE.
HAPPIER CUSTOMERS.**